
Phase III Removal Assessment: Equipment Inventory



Loft Storage Area

Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Cabinet

Location Number: 8

Sample Number at Location:

Description of Sample Location:


Base of wood cabinet



Sample Number at Location: 2

Description of Sample Location:

Top surface of cabinet



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Top of inside shelf



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area

Item Type: Cart / Dolly

Location Number: 18

Sample Number at Location:

Description of Sample Location:


Wheel - 7" dia, 2" wide



Sample Number at Location: 2


Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area

Item Type: Inventory

Location Number: 12

Sample Number at Location:


Description of Sample Location:

Top of random box on rack



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area

Item Type: Inventory

Location Number: 13

Sample Number at Location:

Description of Sample Location:


Top of random box on rack



Sample Number at Location: 2

Description of Sample Location:

Top of random box on rack



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Inventory

Location Number: 14

Sample Number at Location:


Description of Sample Location:

Top of random box on rack



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Machine

Location Number: 1

Sample Number at Location: 1

Description of Sample Location:


Top surface



Sample Number at Location: 2

Description of Sample Location:

Metal cross brace adjacent to air intake



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Machine

Location Number: 2

Sample Number at Location:


Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Machine

Location Number: 3

Sample Number at Location:


Description of Sample Location:

Top of cylinder



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Machine

Location Number: 4

Sample Number at Location:


Description of Sample Location:

Top of cylinder



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Machine

Location Number: 5

Sample Number at Location:

Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Machine

Location Number: 6

Sample Number at Location:

Description of Sample Location:

Top surface



Sample Number at Location: 2

Description of Sample Location:

Vents at air intake



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area

Item Type: Machine

Location Number: 7

Sample Number at Location:

Description of Sample Location:


Top surface



Sample Number at Location: 2


Description of Sample Location:

Air intake vent, filter should be removed for sample collection



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Machine

Location Number: 9

Sample Number at Location:


Description of Sample Location:

Fan blade



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area

Item Type: Machine

Location Number: 10

Sample Number at Location:


Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Machine

Location Number: 11

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top surface along belt protective guard



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Machine

Location Number: 16

Sample Number at Location: 1

Description of Sample Location:

Top surface adjacent to spindle



Sample Number at Location: 2

Description of Sample Location:

Base



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area

Item Type: Machine

Location Number: 17

Sample Number at Location: 1

Description of Sample Location:


Wheel - 3" dia, 1" wide, sample along bottom surface of wheel



Sample Number at Location: 2

Description of Sample Location:

Base cross member



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Rack

Location Number: 12

Sample Number at Location: 1


Description of Sample Location:

Cross brace



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Rack

Location Number: 13

Sample Number at Location:

Description of Sample Location:

Top of cross member



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area

Item Type: Rack

Location Number: 14

Sample Number at Location:

Description of Sample Location:

Top of cross brace



Phase III Removal Assessment: Equipment Inventory





Room: Loft Storage Area


Item Type: Tool

Location Number: 15

Sample Number at Location:

Description of Sample Location:


Bottom of base



Sample Number at Location: 2

Description of Sample Location:

back side of cage




Phase III Removal Assessment: Equipment Inventory



Machine Tool Room

Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Cabinet

Location Number: 19

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Top of cabinet



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Second shelf from bottom



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Cabinet

Location Number: 20

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of cabinet




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Cardboard box on top of cabinet that exhibits staining



Sample Number at Location: 4

Description of Sample Location:

Bottom shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Cabinet

Location Number: 22

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Back of cabinet




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

2nd shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Cabinet

Location Number: 31

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of cabinet



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Bottom of shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Cabinet

Location Number: 33

Sample Number at Location: 1

Description of Sample Location:


Base foot



Sample Number at Location: 2

Description of Sample Location:

Top surface




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:


Top cabinet



Sample Number at Location: 4


Description of Sample Location:

Bottom shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Cart / Dolly

Location Number: 28

Sample Number at Location:

Description of Sample Location:

Wheel - 5" dia, 1" wide, sample bottom of wheel



Sample Number at Location: 2

Description of Sample Location:

Bottom shelf




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Side of cart



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Inventory

Location Number: 18

Sample Number at Location:


Description of Sample Location:

Sample random box



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Inventory

Location Number: 19

Sample Number at Location:

Description of Sample Location:

Random sample of item in box



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Inventory

Location Number: 21

Sample Number at Location:

Description of Sample Location:

Side of cardboard box



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Inventory

Location Number: 22

Sample Number at Location:


Description of Sample Location:

Metal pipe like item on bottom shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Inventory

Location Number: 23

Sample Number at Location: 1


Description of Sample Location:

Top surface of metal wedge



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Inventory

Location Number: 24

Sample Number at Location:

Description of Sample Location:

Die



Sample Number at Location: 2


Description of Sample Location:

Random scrap metal



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Inventory

Location Number: 25

Sample Number at Location:

Description of Sample Location:

Sample top surface of random box on shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Inventory

Location Number: 30

Sample Number at Location:

Description of Sample Location:

Sample top surface of random box



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Inventory

Location Number: 31

Sample Number at Location:


Description of Sample Location:

Sample top surface of random box



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 1

Sample Number at Location:

Description of Sample Location:

Bottom shelf



Sample Number at Location: 2

Description of Sample Location:

Sample top of motor casing



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 2

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top of motor



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 3

Sample Number at Location:

Description of Sample Location:


Base of machine



Sample Number at Location: 2


Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 4

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 5

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2


Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 6

Sample Number at Location: 1

Description of Sample Location:


Base plate



Sample Number at Location: 2


Description of Sample Location:

Top of motor



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 7

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top of motor



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 8

Sample Number at Location: 1

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 9

Sample Number at Location: 1

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of backside of machine



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 10

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top power supply at the rear of the machine



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 11

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top near power supply



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Machine

Location Number: 12

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Bottom shelf



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Machine

Location Number: 13

Sample Number at Location: 1

Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Machine

Location Number: 14

Sample Number at Location:

Description of Sample Location:


Wheels - 5" dia, 1" wide, sample bottom of wheel



Sample Number at Location: 2

Description of Sample Location:

Top



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 15

Sample Number at Location:

Description of Sample Location:

Base feet



Sample Number at Location: 2

Description of Sample Location:

Bottom shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Machine

Location Number: 16

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Rack

Location Number: 17

Sample Number at Location:

Description of Sample Location:

Bottom leg



Sample Number at Location: 2

Description of Sample Location:

Middle shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Rack

Location Number: 21

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Rack

Location Number: 30

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Metal cross member



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Wood shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Workspace

Location Number: 23

Sample Number at Location: 1

Description of Sample Location:

Bottom shelf



Sample Number at Location: 2

Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Base



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Workspace

Location Number: 24

Sample Number at Location:

Description of Sample Location:


Bottom shelf



Sample Number at Location: 2

Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Base



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Workspace

Location Number: 25

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Bottom shelf




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Workspace

Location Number: 26

Sample Number at Location:

Description of Sample Location:

Base 1



Sample Number at Location: 2

Description of Sample Location:

Base 2




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:


Top surface



Sample Number at Location: 4

Description of Sample Location:

Top surface 2



Sample Number at Location: 5

Description of Sample Location:

Bottom of tool box



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 6

Description of Sample Location:

Bottom shelf



Sample Number at Location: 7

Description of Sample Location:

Top of micro drawer



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Workspace

Location Number: 27

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top surface




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Cross brace



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room


Item Type: Workspace

Location Number: 29

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Shelf




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Top shelf



Phase III Removal Assessment: Equipment Inventory





Room: Machine Tool Room

Item Type: Workspace

Location Number: 32

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Top surface




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Wood shelf



Phase III Removal Assessment: Equipment Inventory



Office

Phase III Removal Assessment: Equipment Inventory





Room: Office


Item Type: Cabinet

Location Number: 1

Sample Number at Location:

Description of Sample Location:

Bottom of cabinet



Sample Number at Location: 2


Description of Sample Location:

Top shelf of cabinet



Phase III Removal Assessment: Equipment Inventory





Room: Office


Item Type: Cabinet

Location Number: 6

Sample Number at Location:


Description of Sample Location:

Sample bottom shelf of book shelf



Phase III Removal Assessment: Equipment Inventory





Room: Office

Item Type: Machine

Location Number: 3

Sample Number at Location: 1


Description of Sample Location:

Back of copier near fan port



Phase III Removal Assessment: Equipment Inventory





Room: Office

Item Type: Machine

Location Number: 5

Sample Number at Location: 1


Description of Sample Location:

Sample air vents at the back of the machine



Phase III Removal Assessment: Equipment Inventory





Room: Office

Item Type: Workspace

Location Number: 2

Sample Number at Location:

Description of Sample Location:


Top surface of desk



Sample Number at Location: 2

Description of Sample Location:

Base of cubicle wall




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Top surface on cubicle top cabinet



Phase III Removal Assessment: Equipment Inventory





Room: Office


Item Type: Workspace

Location Number: 4

Sample Number at Location:

Description of Sample Location:

In Carmen's office, roller chair wheels - 1 7/8 dia, 1/4 wide, sample bottom of wheel



Phase III Removal Assessment: Equipment Inventory



Pressing Room

Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Bin

Location Number: 23

Sample Number at Location: 1

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Cabinet

Location Number: 19

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Top of cabinet



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Inside of cabinet base



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Cabinet

Location Number: 24

Sample Number at Location:

Description of Sample Location:


Wheels - 4" dia, 1" W



Sample Number at Location: 2


Description of Sample Location:

Shelf



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Carts/Dollys

Location Number: 28

Sample Number at Location:

Description of Sample Location:


Wheels - 4" dia, 1 3/4" wide



Sample Number at Location: 2

Description of Sample Location:

Bottom shelf



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Carts/Dollys

Location Number: 29

Sample Number at Location:

Description of Sample Location:


Wheel - 5" dia, 1" wide



Sample Number at Location: 2

Description of Sample Location:

Bottom shelf



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Carts/Dollys

Location Number: 30

Sample Number at Location:

Description of Sample Location:

Wheel - 7" dia, 2 1/2" wide



Sample Number at Location: 2


Description of Sample Location:

top



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Inventory

Location Number: 1

Sample Number at Location:

Description of Sample Location:

Misc scrap metal



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Inventory

Location Number: 2

Sample Number at Location:

Description of Sample Location:

Metal spools



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Inventory

Location Number: 3

Sample Number at Location:

Description of Sample Location:

Die from top shelf



Sample Number at Location: 2

Description of Sample Location:

Die from third shelf



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Die from bottom shelf



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Machine

Location Number: 5

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Feeding tray




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Machine

Location Number: 6

Sample Number at Location:

Description of Sample Location:


Base, around circular disk



Sample Number at Location: 2

Description of Sample Location:

Top of machine




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Feeding tray



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Machine

Location Number: 7

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Machine

Location Number: 8

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Machine

Location Number: 9

Sample Number at Location:

Description of Sample Location:


Base, inside



Sample Number at Location: 2


Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Machine

Location Number: 11

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Machine

Location Number: 12

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Top of Machine



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Machine

Location Number: 13

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of machine




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Base of spool tray



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Machine

Location Number: 14

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of power box



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Machine

Location Number: 15

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of machine




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Base of spool tray



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Machine

Location Number: 16

Sample Number at Location:

Description of Sample Location:


Base of cylinder



Sample Number at Location: 2

Description of Sample Location:

Top of cylinder



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Machine

Location Number: 20

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Cross brace



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Machine

Location Number: 21

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Machine

Location Number: 25

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of motor



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Machine

Location Number: 27

Sample Number at Location: 1

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of motor housing



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Machine

Location Number: 31

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top of machine



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Rack

Location Number: 1

Sample Number at Location:

Description of Sample Location:


Base foot area



Sample Number at Location: 2

Description of Sample Location:

Shelf arm



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Rack

Location Number: 2

Sample Number at Location:

Description of Sample Location:


Foot



Sample Number at Location: 2


Description of Sample Location:

Cross bar



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Rack

Location Number: 3

Sample Number at Location:

Description of Sample Location:


Foot



Sample Number at Location: 2


Description of Sample Location:

2nd shelf from the top



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Rack

Location Number: 4

Sample Number at Location:

Description of Sample Location:


Drum rack foot



Sample Number at Location: 2

Description of Sample Location:

Drum rack cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Drum on rack



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Tool

Location Number: 22

Sample Number at Location:


Description of Sample Location:

Top of surface



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Tool

Location Number: 26

Sample Number at Location: 1

Description of Sample Location:


Wheel



Sample Number at Location: 2

Description of Sample Location:

Top of tank



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Top of plastic housing



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room


Item Type: Tools

Location Number: 2

Sample Number at Location:

Description of Sample Location:

Die, top surface.



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Workspace

Location Number: 10

Sample Number at Location:

Description of Sample Location:

Foot



Sample Number at Location: 2

Description of Sample Location:

Shelf



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Workspace

Location Number: 17

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of work surface



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Workspace

Location Number: 18

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Shelf




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Top of work surface



Phase III Removal Assessment: Equipment Inventory





Room: Pressing Room

Item Type: Workspace

Location Number: 22

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Shelf



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Top surface




Phase III Removal Assessment: Equipment Inventory



Receiving Room

Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room

Item Type: Cabinet

Location Number: 7

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Top of locker



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Top shelf



Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room

Item Type: Cabinet

Location Number:9

Sample Number at Location: 1

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room

Item Type: Cart/Dolly

Location Number: 3

Sample Number at Location:

Description of Sample Location:

Floor board



Sample Number at Location: 2

Description of Sample Location:

Back pannel



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:


Top of boom



Sample Number at Location: 4


Description of Sample Location:

Fork



Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room


Item Type: Inventory

Location Number: 1

Sample Number at Location: 1

Description of Sample Location:

Cardboard



Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room

Item Type: Inventory

Location Number: 8

Sample Number at Location:


Description of Sample Location:

Bottom of cardboard box on shelf



Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room


Item Type: Machine

Location Number: 4

Sample Number at Location:

Description of Sample Location:


Underside of base



Sample Number at Location: 2


Description of Sample Location:

Protective screen



Phase III Removal Assessment: Equipment Inventory






Room: Receiving Room

Item Type: Machine

Location Number: 6


Sample Number at Location:

Description of Sample Location:



Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room


Item Type: Rack

Location Number: I

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 2

Description of Sample Location:

Cross member 12' from ground



Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room

Item Type: Rack

Location Number: 2

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Cross member



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Cross member 12' from ground



Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room


Item Type: Rack

Location Number: 5

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Cross member



Sample Number at Location: 4


Description of Sample Location:

Cross member 12' above ground



Phase III Removal Assessment: Equipment Inventory





Room: Receiving Room


Item Type: Workspace

Location Number: 8

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Metal cross member




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Wooden shelf



Sample Number at Location: 4

Description of Sample Location:




Phase III Removal Assessment: Equipment Inventory



Screw Machine Room

Phase III Removal Assessment: Equipment Inventory





Room: Screw Machine Room

Item Type: Cart/Dolly

Location Number: 3

Sample Number at Location:

Description of Sample Location:


Wheels -8" dia, 2" wide



Sample Number at Location: 2


Description of Sample Location:

Wood platform



Phase III Removal Assessment: Equipment Inventory





Room: Screw Machine Room

Item Type: Machine

Location Number: I

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Top of control pannel



Phase III Removal Assessment: Equipment Inventory





Room: Screw Machine Room


Item Type: Machine

Location Number: 2

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Top of motor



Phase III Removal Assessment: Equipment Inventory





Room: Screw Machine Room

Item Type: Tool

Location Number: 4

Sample Number at Location: 1

Description of Sample Location:


Bottom of base



Sample Number at Location: 2


Description of Sample Location:

Back of protective screen



Phase III Removal Assessment: Equipment Inventory





Room: Screw Machine Room

Item Type: Tool

Location Number: 5

Sample Number at Location:

Description of Sample Location:

Top of motor




Phase III Removal Assessment: Equipment Inventory



Shipping Office

Phase III Removal Assessment: Equipment Inventory





Room: Shipping Office


Item Type: Workspace

Location Number: 1

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Wheel of chair




Phase III Removal Assessment: Equipment Inventory



Shipping Room

Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room

Item Type: Cabinet

Location Number: 7

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2


Description of Sample Location:

2nd shelf



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room

Item Type: Cabinet

Location Number: 8

Sample Number at Location: 1

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Vent area




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Inside top shelf



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Cabinet

Location Number: 11

Sample Number at Location:

Description of Sample Location:

Base




Sample Number at Location: 2

Description of Sample Location:



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Cabinet

Location Number: 13

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Cart/Dolly

Location Number: 10

Sample Number at Location:


Description of Sample Location:

Wheels - 7" dia, 2.5" wide



Sample Number at Location: 2

Description of Sample Location:



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Cart/Dolly

Location Number: 12

Sample Number at Location:

Description of Sample Location:

Wheel - 10" dia, 2.5" wide



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room

Item Type: Cart/Dolly

Location Number: 15

Sample Number at Location: 1

Description of Sample Location:


Floor board



Sample Number at Location: 2

Description of Sample Location:

Back pannel




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Roof cage



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room

Item Type: Cart/Dolly

Location Number: 16

Sample Number at Location:


Description of Sample Location:

Wheel - 7" dia, 2" wide



Sample Number at Location: 2

Description of Sample Location:




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Fork



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room

Item Type: Inventory

Location Number: 1

Sample Number at Location:

Description of Sample Location:

Cardboard box



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room

Item Type: Inventory

Location Number: 7

Sample Number at Location:

Description of Sample Location:

Random item that appears to have been there for awhile



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Machine

Location Number: 3

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Top of metal housing



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Machine

Location Number: 5

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2


Description of Sample Location:

Flat surface on interior of machine



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Machine

Location Number: 9

Sample Number at Location: 1

Description of Sample Location:


Wheel - 3" dia, 1" wide



Sample Number at Location: 2

Description of Sample Location:

Side of cabinet



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Machine

Location Number: 14

Sample Number at Location: 1

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Foot peddle



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Machine

Location Number: 17

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

circular disk



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:


Top of bottom plate



Sample Number at Location: 4

Description of Sample Location:

Top of column



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Machine

Location Number: 18

Sample Number at Location:

Description of Sample Location:


Vent



Sample Number at Location: 2


Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Machine

Location Number: 19

Sample Number at Location:

Description of Sample Location:

back side of fridge



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Rack

Location Number: 1

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Cross member



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Wood shelf



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Rack

Location Number: 2

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Cross member



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Wood shelf



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room

Item Type: Workspace

Location Number: 4

Sample Number at Location:

Description of Sample Location:

Bottom shelf



Sample Number at Location: 2

Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Shipping Room


Item Type: Workspace

Location Number: 6

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Top cardboard surface




Phase III Removal Assessment: Equipment Inventory



Show Room

Phase III Removal Assessment: Equipment Inventory





Room: Show Room


Item Type: Cabinet

Location Number: I

Sample Number at Location:

Description of Sample Location:

Bottom shelf



Sample Number at Location: 2

Description of Sample Location:

Top shelf



Phase III Removal Assessment: Equipment Inventory





Room: Show Room


Item Type: Cabinet

Location Number: 2

Sample Number at Location:

Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Show Room


Item Type: Cabinet

Location Number: 3

Sample Number at Location: 1

Description of Sample Location:

Top of cabinet




Phase III Removal Assessment: Equipment Inventory



Sort / Packing Room

Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Cabinet

Location Number: 11

Sample Number at Location:

Description of Sample Location:


Top of cabinet



Sample Number at Location: 2

Description of Sample Location:

Bottom shelf




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Base of cabinet along the floor



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room

Item Type: Inventory

Location Number: 2

Sample Number at Location:


Description of Sample Location:

Top surface of random item on shelf



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room

Item Type: Inventory

Location Number: 10

Sample Number at Location:

Description of Sample Location:


Random item on shelf



Sample Number at Location: 2


Description of Sample Location:

Top of speaker on shelf



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Inventory

Location Number: 11

Sample Number at Location:


Description of Sample Location:

Random item inside cabinet



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Inventory

Location Number: 12

Sample Number at Location:

Description of Sample Location:

Random item on shelf



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room

Item Type: Inventory

Location Number: 13

Sample Number at Location:


Description of Sample Location:

Metal strips under bench



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Machine

Location Number: 1

Sample Number at Location:

Description of Sample Location:


Top surface of machine



Sample Number at Location: 2

Description of Sample Location:

Base of foot peddle



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:


Base of table



Sample Number at Location: 4


Description of Sample Location:

Top surface of table



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Machine

Location Number: 3

Sample Number at Location:

Description of Sample Location:

Top surface above glass case



Sample Number at Location: 2


Description of Sample Location:

Foot of table



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Machine

Location Number: 4

Sample Number at Location:

Description of Sample Location:


Side of motor



Sample Number at Location: 2


Description of Sample Location:

Base of leg



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Machine

Location Number: 5

Sample Number at Location:

Description of Sample Location:

Top of machine above main switch



Sample Number at Location: 2


Description of Sample Location:

Base of leg



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Rack

Location Number: 2

Sample Number at Location:

Description of Sample Location:


Base of leg



Sample Number at Location: 2

Description of Sample Location:

Cross brace



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Surface of wood shelf



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room

Item Type: Rack

Location Number: 10

Sample Number at Location:

Description of Sample Location:


Bottom of leg



Sample Number at Location: 2

Description of Sample Location:

Second shelf from top




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3


Description of Sample Location:

Metal cross member, under wood shelf



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Tool

Location Number: 11

Sample Number at Location: 1


Description of Sample Location:

Air hose - 5/8" diameter



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Workspace

Location Number: 6

Sample Number at Location: 1

Description of Sample Location:

Top surface of work space



Sample Number at Location: 2

Description of Sample Location:

Bottom of wood base



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Top of machine under bench



Sample Number at Location: 4

Description of Sample Location:


Bottom of foot peddle



Sample Number at Location: 5

Description of Sample Location:

Bottom of wheel - 3 1/4 dia, 1 1/4" wide



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Workspace

Location Number: 7

Sample Number at Location: 1

Description of Sample Location:

Top of bench



Sample Number at Location: 2

Description of Sample Location:

Top of machine under bench



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Bottom of wood platform under machine



Sample Number at Location: 4


Description of Sample Location:

Bottom of wooden support



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room

Item Type: Workspace

Location Number: 8

Sample Number at Location:

Description of Sample Location:

Top of workspace



Sample Number at Location: 2

Description of Sample Location:

Base of foot




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:


Top of machine under workspace



Sample Number at Location: 4

Description of Sample Location:

Bottom of wheels - 3 1/4" dia, 1 1/4" wide



Sample Number at Location: 5

Description of Sample Location:

Bottom of foot peddle



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room


Item Type: Workspace

Location Number: 9

Sample Number at Location:

Description of Sample Location:


Top surface of work area



Sample Number at Location: 2

Description of Sample Location:

Top of shelf under bench



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Bottom of wheels - 3 1/4" dia, 1 1/4" wide



Sample Number at Location: 5


Description of Sample Location:

Base of machine to side of the workspace



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room

Item Type: Workspace

Location Number: 12

Sample Number at Location:

Description of Sample Location:


Top surface



Sample Number at Location: 2


Description of Sample Location:

Bottom shelf



Phase III Removal Assessment: Equipment Inventory





Room: Sort / Packing Room

Item Type: Workspace

Location Number: 13

Sample Number at Location: 1

Description of Sample Location:

Top surface of workspace



Sample Number at Location: 2

Description of Sample Location:

Bottom of wooden base




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Top of shelf under workspace




Phase III Removal Assessment: Equipment Inventory



Storage Room

Phase III Removal Assessment: Equipment Inventory





Room: Storage Room

Item Type: Cart / Dolly

Location Number: 3

Sample Number at Location: 1

Description of Sample Location:


Wheel - 5" dia, 1" wide



Sample Number at Location: 2


Description of Sample Location:

Bottom shelf



Phase III Removal Assessment: Equipment Inventory





Room: Storage Room


Item Type: Cart / Dolly

Location Number: 4

Sample Number at Location:

Description of Sample Location:


Wheels -5" dia, 1.5" wide



Sample Number at Location: 2

Description of Sample Location:

Cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Shelf



Phase III Removal Assessment: Equipment Inventory





Room: Storage Room


Item Type: Machine

Location Number: 2

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Shelf




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Top surface



Phase III Removal Assessment: Equipment Inventory





Room: Storage Room


Item Type: Rack

Location Number: 7

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:


Cross member



Sample Number at Location: 4


Description of Sample Location:

Cross member



Phase III Removal Assessment: Equipment Inventory





Room: Storage Room


Item Type: Tool

Location Number: 5

Sample Number at Location:

Description of Sample Location:

Bottom of base



Sample Number at Location: 2

Description of Sample Location:

back of protective cage



Phase III Removal Assessment: Equipment Inventory





Room: Storage Room

Item Type: Tool

Location Number: 6

Sample Number at Location: 1

Description of Sample Location:


Bottom of base



Sample Number at Location: 2

Description of Sample Location:

Top of L-bracket



Phase III Removal Assessment: Equipment Inventory





Room: Storage Room


Item Type: Workspace

Location Number: I

Sample Number at Location:

Description of Sample Location:

Bottom of foot



Sample Number at Location: 2

Description of Sample Location:

Wooden shelf




Phase III Removal Assessment: Equipment Inventory



Warehouse / Inventory Area

Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area

Item Type: Inventory

Location Number: 1

Sample Number at Location:


Description of Sample Location:

Random box



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area

Item Type: Inventory

Location Number: 2

Sample Number at Location:

Description of Sample Location:

Random box



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area

Item Type: Inventory

Location Number: 3

Sample Number at Location:


Description of Sample Location:

Random item



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area

Item Type: Inventory

Location Number: 4

Sample Number at Location:


Description of Sample Location:

Random item



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area

Item Type: Inventory

Location Number: 5

Sample Number at Location:


Description of Sample Location:

Random item



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area


Item Type: Rack

Location Number: 1

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Cross member



Sample Number at Location: 4


Description of Sample Location:

Cross member 12' above ground



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area


Item Type: Rack

Location Number: 2

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Cross member



Sample Number at Location: 4

Description of Sample Location:

Cross member 12' above the ground



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area

Item Type: Rack

Location Number: 3

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

Cross member



Sample Number at Location: 4


Description of Sample Location:

Cross member from 12' above the ground



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area


Item Type: Rack

Location Number: 4

Sample Number at Location:

Description of Sample Location:


Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 4

Description of Sample Location:

Cross member



Sample Number at Location: 5


Description of Sample Location:

Cross member 12' above the ground



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area

Item Type: Rack

Location Number: 5

Sample Number at Location:

Description of Sample Location:

Base



Sample Number at Location: 2

Description of Sample Location:

Cross brace




Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:


Cross member



Sample Number at Location: 4


Description of Sample Location:

Cross member 12' above the ground



Phase III Removal Assessment: Equipment Inventory





Room: Warehouse / Inventory Area

Item Type: Tool

Location Number: 6

Sample Number at Location:

Description of Sample Location:


Rubber foot



Sample Number at Location: 2

Description of Sample Location:

2 run



Phase III Removal Assessment: Equipment Inventory



Sample Number at Location: 3

Description of Sample Location:

second ladder bottom feet

